

NORMAL - UNCLASSIFIED EFTO

FROM: WR-ALC/LKCB, ROBINS AFB GA 31098

TO: AFRL ROBINS AFB GA//MLS-OLR//  
ANGRC ANDREWS AFB MD//LG/SE//  
HQ ACC LANGLEY AFB VA//LG/SE//  
HQ AETC RANDOLPH AFB TX//LG/SE//  
HQ AFRC ROBINS AFB GA// LG/SE//  
HQ AFSOC HULBERT FLD FL//LG/SE//  
HQ AFSPC PETERSON AFB CO//LG/SE//  
HQ AMC SCOTT AFB IL//LG/SE//  
HQ PACAF HICKAM AFB HI//LG/SE//  
HQ USAFE RAMSTEIN AB GE//LG/SE//  
HQ AFMC WRIGHT PATTERSON AFB OH//DOM/LG/SE//  
HQ AFSA KIRTLAND AFB NM//SE//  
OC-ALC TINKER AFB OK//LC/LH/LAK/LAB/LAL//SE/TI/TIE/TILUB//  
OO-ALC HILL AFB UT//LF/LC/LAC/LIL/SE/TI/TIE//  
WR-ALC ROBINS AFB GA//LA/LB/LC/LE/LF/LJ/LK/LU/LR/SE/TI/TIE//  
ASC WRIGHT PATTERSON AFB OH//FB/FBA/FBJ/GR/LU/SE/RA/YT/YC/YD/YF/YN/YP/YS//

INFO: HQ USAF WASHINGTON DC//LGMM/LGSS//  
AFMC/AFRL WRIGHT PATTERSON AFB OH//MLSS/MLSA/ENIS//

UNCLAS EFTO

SUBJ: INTERIM SAFETY SUPPLEMENT 1-1-3SS-1 DATED 11 SEPTEMBER 2001 (INSPECTION AND REPAIR OF AIRCRAFT INTEGRAL TANKS AND FUEL CELLS)

1. THIS PULICATION SUPPLEMENTS T.O. 1-1-3, DATED 30 NOVEMBER 1994, TITLE: INSPECTION AND REPAIR OF AIRCRAFT INTEGRAL FUEL TANKS AND FUEL CELLS. A SUITABLE REFERENCE TO THIS SUPPLEMENT WILL BE MADE ON THE TITLE PAGE OF THE BASIC PUBLICATION. COMMANDERS ARE RESPONSIBLE FOR BRINGING THIS SUPPLEMENT TO THE ATTENTION OF ALL AFFECTED PERSONNEL. MAJCOMS, FOAS AND DRUS ARE RESPONSIBLE FOR RETRANSMITTING THIS ISS TO SUBORDINATE UNITS NOT INCLUDED AS ADDRESSEES ON THIS MESSAGE.

2. DISTRIBUTION STATEMENT: APPROVED FOR PUBLIC RELEASE; DISTRIBUTION IS UNLIMITED. QUESTIONS CONCERNING TECHNICAL CONTENT SHOULD BE ADDRESSED TO WR-ALC/LES GF, 295 BYRON ST, ROBINS AFB GA. 31098-1640.

3. PURPOSE: THIS SUPPLEMENT IS ISSUED TO AMEND THE BASIC PUBLICATION ON MEDICAL TREATMENT AND PROTECTIVE CLOTHING AND EQUIPMENT REQUIREMENTS PERTAINING TO FUEL CONTACT.

4. INSTRUCTIONS:

A. PAGE 2-4. PARAGRAPH 2-5.2.1.

1. INSERT A NEW FOURTH SENTENCE TO READ: SKIN MUST BE THOROUGHLY CLEANSED OF ANY FUEL WITH MILD SOAP AND WATER.

2. CHANGE LAST SENTENCE TO READ: MEDICAL ATTENTION SHALL BE OBTAINED IF ABNORMAL CONDITIONS OR SYMPTOMS DEVELOP OR IF RECOMMENDED ON THE MSDS.

B. PAGE 2-4. PARAGRAPH 2-6.1.1. CHANGE PARAGRAPH TO READ AS FOLLOWS:

2-6.1.1. COVERALLS. PERSONNEL PERFORMING MAINTENANCE IN FUEL SYSTEMS REPAIR AREAS/FACILITIES SHALL WEAR APPROVED COVERALLS TO ELIMINATE THE POSSIBILITY OF CREATING A STATIC ELECTRICITY DISCHARGE. THE COVERALL MATERIAL MUST BE STATIC-RESISTANT AND BUTTONS OR TABS MUST BE NON-SPARKING. THE COVERALLS MUST OFFER ADEQUATE PROTECTION FROM LIQUID PENETRATION WITHOUT A SIGNIFICANT INCREASE IN HEAT STRESS LEVELS. WHITE IS THE PREFERRED COLOR FOR ALL CLOTHING, HOWEVER, OTHER COLORS ARE ACCEPTABLE. ALL COVERALLS WILL BE THOROUGHLY WASHED AFTER USE. PERSONNEL SHALL NOT USE COVERALLS THAT HAVE NOT BEEN WASHED OR HAVE ANY RESIDUE. COVERALLS WITH EXCESSIVE DRIED SEALANT OR STAINS WILL BE DISCARDED. CARE SHOULD BE TAKEN TO ENSURE LOOSE BUTTONS DO NOT SNAG ON FUEL SYSTEM COMPONENTS AND BECOME TORN LOOSE.

C. PAGE 2-4. PARAGRAPH 2-6.1.2. FIRST SENTENCE. ADD THE FOLLOWING TEXT AFTER THE WORD CLOTHING: (I.E. COVERALLS, FOOTWEAR, GLOVES).

D. PAGE 2-4. PARAGRAPH 2-6.1.3. REPLACE THE LAST SENTENCE WITH THE FOLLOWING: STATIC-RESISTANT SOCKS OR BOOTIES SHALL BE WORN. ENSURE THE SOCKS/BOOTIES ARE CLEAN AND SERVICEABLE.

E. PAGE 2-4. PARAGRAPH 2-6.1.4. SECOND SENTENCE. REPLACE THE WORD "COTTON" WITH THE WORDS "STATIC-RESISTANT"

5. THE TECHNICAL CONTENT MANAGER FOR THIS SUPPLEMENT IS RAY COURINGTON, WR-ALC/LESGF, DSN 468-7046 EXT 119/COMM 478-926-7046 EXT 119, EMAIL [HOLLIE.COURINGTON@ROBINS.AF.MIL](mailto:HOLLIE.COURINGTON@ROBINS.AF.MIL). THE TO MANAGER FOR THIS SUPPLEMENT IS JOE MICIK, WR-ALC/LKCB, DSN 468-0899/COMM 478-926-0899, EMAIL [JOSEPH.MICIK@ROBINS.AF.MIL](mailto:JOSEPH.MICIK@ROBINS.AF.MIL).

THE END